

Code 015

1 1 APR 1968

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6 SERIES

THIRD ENDORSEMENT on CO, VT-2, accident, Ser 6-68A, concerning T-28C, BUNO 146259, of 2 Mar 1968, pilot JONES

From: Chief of Naval Air Training

To: Commander, Naval Aviation Safety Center

Subj: Aircraft accident report; forwarding of

1. Forwarded, concurring in the conclusions and recommendations of the Aircraft Accident Board and comments and action indicated in the second endorsement.

(b) (6)

Copy to:

CNABATRA

COMNAVAIRSYSCOM (AIR 404)

NAVAIRSYSCOM, NAVPLANTREPO, Columbus

CO, NAVAERORECOVPAC, El Centro

DIR, AFIP

CO, TRARON TWO

Chief of Staff
(Acting)

Code 015
5 APR 1968

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6
SERIES

SECOND ENDORSEMENT on TRARON TWO, accident, serial 6-68A,
concerning T-28C, BuNo 146259, of 2 March 1968, pilot JONES

From: Chief of Naval Air Basic Training
To: Commander, Naval Aviation Safety Center
Via: Chief of Naval Air Training

Subj: Aircraft Accident Report; forwarding of

1. Forwarded, concurring with the conclusions and recommenda-
tions of the Aircraft Accident Board.

(b) (5)

Copy to:
NAVAVNSAFCEW (2 direct)
NAVAIRSYSCOM HQ
NAVPLANTREPO COLUMBUS
CO NAVAERORECFAC
DIR AFIP
TRARON TWO


D. H. GUINN

26 March 1968

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6 SERIES

FIRST ENDORSEMENT on TRARON TWO AAR 6-68A concerning T-28C BUNO 146259
occurring 2 March 1968

From: Commanding Officer, Training Squadron TWO
To: Commander, U. S. Naval Aviation Training Center
Via: (1) Chief of Naval Air Basic Training
(2) Chief of Naval Air Training

Subj: Training Squadron TWO AAR 6-68A; forwarding of

1. Forwarded, concurring in the conclusions and recommendations of the
basic report.



A. B. DAVIS

Copy to:
NAVAVISAFSCEN (2)
NAVAIRSYSCOM
CNATRA
CNABATRA
NAVPLANTREPO COLUMBUS

PART 1 GENERAL									
1. AIRCRAFT ACCIDENT BOARD APPOINTED BY	2. SERIAL NO.	3. DTG (LOCAL) OF MISHAP	4. MODEL AIRCRAFT	5. BUREAU NUMBER					
C.O. TRARON TWO	6-68A	0209173 MAR 68	T-28C	146259					
6. TO: Commander, Naval Aviation Safety Center	7. VIA: CNABATRA CNATRA	8. N/A	9. LOCATION OF MISHAP	10. DAMAGE					
			1/2 MILE SE CHOCTAW FIELD	ALFA					
		11. TIME OF DAY	12. TIME IN FLIGHT	13. FLIGHT CODE					
		DAY	0.5	1D1					
		14. CLEARED	FROM NAAS WHITING FLD TO NAAS WHITING FLD						
		15. TYPE CLEARANCE	16. AIRSPEED	17. A/C WEIGHT					
		VFR	90 KTS (E)	7862					
18. BRIEF DESCRIPTION OF MISHAP			19. ELEVATION AT TIME OF MISHAP						
IN FLIGHT FIRE, UNCONTROLLED COLLISION WITH GROUND			S.L. 100' TERRAIN 0						
20. LIST MODEL, BUNG, REPORTING CUSTOMER AND DAMAGE CLASSIFICATION OF ANY OTHER A/C INVOLVED (Template OPNAV Form 3750-1 for each A/C)									
NONE									

(b) (5)

SECTION C PERSONNEL DATA									
1. NAME (Last, first, & middle initial)		2. GRADE	3. TITLE	4. DUTY STATION	5. GRADE	6. DUTY STATION	7. GRADE	8. DUTY STATION	9. GRADE
PILOT (at controls at time of mishap)		LTJG	(b) (6)	USN	24	1	INST	R/C	A
CO-PILOT		LTJG	(b) (6)	USNR	24	1 YEAR	STUD	F/C	B
ITEM		ITEM		ITEM		ITEM		ITEM	
11. ALL MODELS		853		17. ON LANDINGS DAY/NIGHT		ALL		14 / 0	
12. ALL MODELS IN LAST 12 MONTHS		553		18. PCLP LANDINGS LAST 6 MONTHS DAY/NIGHT		IN MODEL		14 / 0	
13. ALL MODELS IN LAST 3 MONTHS		119		19. INSTRUMENT HOURS LAST 3 MONTHS ACTUAL/SIMULATED		ALL		0 / 0	
14. ALL SERIES THIS MODEL		A/C 663		20. NIGHT HOURS LAST 3 MONTHS		IN MODEL		2.4 / 0	
15. ALL SERIES THIS MODEL LAST 12 MONTHS		OFT/OPT 0 / 20EST		21. TOTAL HOURS IN JETS (if jet mishap) HELIOS (if helo mishap)		ALL		3.8 / 0	
16. ALL SERIES THIS MODEL LAST 3 MONTHS		A/C 553		22. LAST PRIOR FLIGHT ALL SERIES THIS MODEL		DATE		1 MAR 68	
		OFT/OPT 0 / 0				DURATION		1.5	
23. DATE/GRADE LAST NATOPS STANDARDIZATION CHECK				16 OCT 67/SAT.				24. TYPE INSTRUMENT CARD	
								STANDARD	
25. NAME (Last, first, & middle initial)		26. GRADE	27. DUTY STATION	28. GRADE	29. DUTY STATION	30. GRADE	31. DUTY STATION	32. GRADE	33. DUTY STATION
NONE									

AIRCRAFT ACCIDENT REPORT

OPNAV FORM 3750-1A (Rev. 3-63) Page 2

SPECIAL HANDLING REQUIRED in accordance with
Para. 46, OPNAV INSTRUCTION 3750.6, 1963 edition

OPNAV REPORT 3750-1

PART 1. GENERAL

1. AIRCRAFT ACCIDENT BOARD APPOINTED BY C.O. TRACON TWO	2. SERIAL NO. 6-68A	3. UTS (LOCAL) OF MISHAP 020917S MAR 68	4. MODEL AIRCRAFT T-28C	5. BUREAU NUMBER 146259
6. TO: Commander, Naval Aviation Safety Center		9. LOCATION OF MISHAP		
7. VIA	11. TIME OF DAY	12. TIME IN FLIGHT	13. FLIGHT CODE	
14. CLEARED FROM		14. CLEARED TO		
15. TYPE CLEARANCE		16. AIRSPEED	17. A/C WEIGHT	
18. BRIEF DESCRIPTION OF MISHAP		19. ELEVATION AT TIME OF MISHAP S. L. TENBUN		
20. LIST MODEL, BUREAU, REPORTING CUSTODIAN AND DAMAGE CLASSIFICATION OF ANY OTHER A/C INVOLVED (Complete OPNAV Form 3750-1 for each A/C)				

(b) (5)

1. NAME (Last, first, & middle initial) PILOT (at controls at time of mishap)	2. GRADE LTJG	3. UTS (b) (6)	4. UTS USNR	5. UTS 24	6. UTS 1 YEAR	7. UTS NFC	8. UTS STUD	9. UTS F/C	10. UTS B
11. ALL MODELS 35		17. OV LANDINGS DAY/NIGHT ALL 0 IN MODEL		18. FCPL LANDINGS LAST 6 MONTHS DAY/NIGHT ALL 0 IN MODEL		19. INSTRUMENT HOURS LAST 3 MONTHS ACTUAL/SIMULATED ALL 0 IN MODEL		20. NIGHT HOURS LAST 3 MONTHS ALL 0 IN MODEL	
12. ALL MODELS IN LAST 12 MONTHS 35		21. TOTAL HOURS IN JETS (if jet mishap) HELICO (if helo mishap)		22. LAST PRIOR FLIGHT ALL SERIES THIS MODEL DATE 28 FEB 1966 DURATION 1.5		23. DATE/GRADE LAST NATOPS STANDARDIZATION CHECK N/A		24. TYPE INSTRUMENT CARD NONE	
13. ALL MODELS IN LAST 3 MONTHS 35		25. NAME (Last, first, & middle initial)		26. GRADE		27. UTS		28. UTS	
14. ALL SERIES THIS MODEL A/C 6.0 OFT/OTF		29. SEARCH OF RECORDS		30. UTS		31. UTS		32. UTS	
15. ALL SERIES THIS MODEL LAST 12 MONTHS A/C 6.0 OFT/OTF		33. UTS		34. UTS		35. UTS		36. UTS	
16. ALL SERIES THIS MODEL LAST 3 MONTHS A/C 6.0 OFT/OTF		37. UTS		38. UTS		39. UTS		40. UTS	

AIRCRAFT ACCIDENT REPORT

OPNAV FORM 3750-17 (Rev. 3-63) Page 3

SPECIAL HANDLING REQUIRED in accordance with

Para. 66, OPNAV INSTRUCTION 3750.6, effective edition

OPNAV REPORT 3750-1

PART II MAINTENANCE, MATERIAL AND FACILITIES DATA														
A. A/C HISTORY	1. DATE OF MANUFACTURE	2. FLIGHT HRS. SINCE ACCEPTANCE	3. NO. OF PAR/OVERHAUL	4. MONTHS SINCE LAST PAR/OVERHAUL	5. FLT HRS. SINCE LAST PAR/OVERHAUL	6. LAST/PAR OVERHAUL ACTIVITY	7. TYPE OF LAST CHECK PERFORMED	8. FLIGHT HOURS SINCE LAST CHECK	9. DAYS SINCE LAST CHECK					
	0-15-56	5405.8	3	8	421.4	PNS	CALENDAR ODD	2.5	2					
	B. ENGINE HISTORY	1. ENGINE MODEL	2. ENGINE SERIAL NUMBER	3. FLIGHT HRS. SINCE ACCEPTANCE	4. NUMBER OF OVERHAULS	5. WAS DIR REQUESTED	6. FLT HRS. SINCE LAST OVERHAUL	7. LAST OVERHAUL ACTIVITY	8. TYPE OF LAST CHECK PERFORMED	9. FLIGHT HOURS SINCE LAST CHECK	10. DAYS SINCE LAST CHECK			
		1R1820-86A	520791	4723.8	6	YES	425.4	PNS	CALENDAR ODD	2.5	2			
		(2)												
(3)														
(4)														
C. COMPONENT HISTORY	1. COMPONENT INVOLVED NOMENCLATURE	2. MANUFACTURER'S PART NUMBER	3. TOTAL HRS ON PART	4. NO. OF OVERHAULS	5. HOURS SINCE LAST OVERHAUL	6. OVERHAUL ACTIVITY	7. WAS DIR REQUESTED	8. SER. NO. FOR AMPER						
	(1)													
	(2)													
	(3)													
	(4)													
D. INCIDENTS & GROUND ACCIDENTS	1. PARTS REPAIRED		2. PARTS REPLACED		3. DIRECT HOURS INVOLVED									
	PART NUMBER	NOMENCLATURE	PART NUMBER	NOMENCLATURE										
E. ENGINE FAILURES	JET ENGINE FLAMEOUT (Include intentional securing to prevent engine damage)													
	AT TIME OF FLAMEOUT	1. ALTITUDE	2. IAS	3. RPM	4. EGT	5. MANEUVER AT TIME OF FLAMEOUT	6. FUEL FLOW	7. ALTITUDE						
	8. G FORCES	9. RELIGHT	10. ALTITUDE	11. IAS	12. MAX EGT	13. FUEL CONTROL	14. NO. RELIGHT ATTEMPTS							
		<input type="checkbox"/> ATTEMPTED <input type="checkbox"/> ACCOMPLISHED				<input type="checkbox"/> PRIMARY <input type="checkbox"/> MANUAL								
	INTENTIONAL SECURE	15. ENGINE SYMPTOMS	16. CAUSE OF SYMPTOMS											
RECIPROCATING ENGINE FAILURE														
17. ALTITUDE	18. IAS	19. ALTITUDE	20. RPM	21. MAP	22. TORQUE/BMEP	23. FUEL FLOW PRESSURE	24. OIL PRESSURE							
INTENTIONAL SECURE	25. ENGINE SYMPTOMS	26. CAUSE OF SYMPTOMS												
F. OTHER REPORT	IDENTIFY OTHER REPORTS CONCERNING THIS MISAP													
	1. AMPER SERIAL NUMBER: NONE													
	2. DIR MESSAGE REQUEST DATE-TIME-GROUP: See Below													
	3. OTHER: PRELIMINARY MESSAGE DTG 022035Z MAR 68													
	4. SUPPLEMENTARY MESSAGE DTG 031610Z MAR 68 DIR on engine and components TRARON TWO messages DTG's: 061610Z, 061614Z, 061616Z, 061618Z, 061620Z, All MAR 68.													

AIRCRAFT ACCIDENT REPORT

SPECIAL HANDLING REQUIRED in accordance with

OPNAV REPORT 3750-1

OPNAV FORM 3750-1A (Rev. 3-63) P1

Form No. OPNAV INSTRUCTION 3750.6 (Rev. 6-63)

1. EQUIPMENT INVOLVED <input type="checkbox"/> CATAPULT <input type="checkbox"/> ARRESTING GEAR		2. PRESSURE SETTING	3. WIND OVER DECK	4. RELATIVE WIND	5. APPROACH/END SPEED
6. MARK NUMBER	7. MODEL NUMBER	8. LOCATION OF SHIP	9. LAUNCHING BRIGLE AND BRIGLE ARRESTER		

N/A

10. CATAPULT/ARRESTING GEAR BULLETINS OR MONOGRAMS USED

G. SHIPS DATA

11. This portion shall be completed whenever (1) an aircraft accident involves arresting gear barrier and/or barricade equipment or (2) an aircraft accident involves malfunctioning of arresting gear, barrier and/or barricade equipment. Incidents or routine damage to cables, weldings and other expendable equipment need not be reported herein.

ENGAGED	12. DECK RUNOUT (FEET)	13. RAM TRAVEL (INCHES)	14. CONTROL VALVE SETTINGS		15. ACCUMULATOR PRESSURE (PSI)	16. COMMENTS (for cable failures specify no. landings and months in service)
			CONSTANT PRESSURE DOME (P.S.I.)	CONSTANT RUNOUT (WT. LBS.)		
DECK PENDANT						
DECK PENDANT						
BARRIER/ BARRICADE						

I. WEATHER H. DEPLOYMENT

FOR ACCIDENTS ABOARD CARRIERS (complete on pilot)		
1. DATE DEPLOYED COMUS	3. DAY HOURS/LANDINGS SINCE DEPLOYMENT	4. DAY HOURS/LANDINGS LAST 30 DAYS
2. NO. DAYS OPERATING PERIOD		
5. INST. HOURS LOGGED SINCE DEPLOYMENT ACTUAL/SIMULATED	6. NIGHT HOURS/LANDINGS SINCE DEPLOYMENT	7. NIGHT HOURS/LANDINGS LAST 30 DAYS
WEATHER AT SCENE OF MISHAP		
1. CEILING 10,000	2. VISIBILITY 7	3. RELATIVE WIND DIRECTION AND VELOCITY 260° 10 knots (true)
4. TEMPERATURE RUNWAY OUTSIDE AIR 50		5. DLEW POINT 40
6. ALTITUDE SETTING 30.13		
7. OTHER WEATHER CONDITIONS: (for use aloft, wing level, and other, describe as appropriate)		
NONE		

PART III ADDITIONAL INFORMATION

PART	SECTION	ITEM	1. REMARKS	2. COPY DISTRIBUTION
				2cc NAVJAG/FECH DIRECT (ARI) 1cc N.V.A.L.SYS COM HQ 1cc CNABATRA 1cc CNATRA 1cc N.V.PLANTREPO COLUMBUS 1cc C.O. NAVAERO RECFAC 1cc AFIP 1cc TR/CONTWO FILES
COST DAMAGE TO:			3. GOVERNMENT PROPERTY	4. PRIVATE PROPERTY

PART IV SIGNATURES OF	
1. COMMANDER	2. WITNESS
3. FLIGHT	4. FLIGHT
5. FLIGHT	6. FLIGHT

5. LT (b) (6) ASST AV SAF OFF

OP-054

THE ACCOUNT

Part V - The Accident

T-28 BuNo 146259, Side No. 20-250, departed NAAS Whiting Field at 0847 2 March 1968, on a duly authorized Transition 6 dual syllabus training hop. Prior to departure the aircraft was pre-flight inspected by the student and instructor pilots. The student checked the top portion and the instructor checked the bottom of the aircraft. An inflight test for carbon monoxide fumes was to be conducted as part of a check-out of a "strong burning smell.." discrepancy written up by the same instructor on the previous day.

The start, taxi, engine run-up and take-off were normal. After take-off the aircraft was turned to the north and a 170 knot climb commenced to conform to local course rules. As the aircraft passed 1500 feet, a turn to 180° was commenced to enter the L-5 area.

(b) (5)

(b) (5)



The aircraft was observed to go into a slight dive, about 10° nose down, then level off after several hundred feet of descent. Then the left wing dropped about 15° and the aircraft nosed over, starting at about 4000 feet, into a steep dive. Somewhere after commencing the dive, the instructor attempted bailout, probably about 2500 feet. (b) (5)

PAGE 6 of 17 PAGES

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6 SERIES

(b) (5)

The aircraft impacted about one half mile south east of Chocktaw Field. The impact angle was about 70° the wings were level and the aircraft upright. The instructor pilot landed 120 yards short of the aircraft along the flight path with no apparent attempt having been made to pull his parachute "D" ring. The student pilot landed approximately one mile south east of the aircraft and sat on top of his parachute awaiting rescue.

The mishap was reported just after impact by the pilot of T-28 side No. 200, the pilots of which witnessed the entire crash. Search and Rescue efforts were begun and the student pilot was picked up at 0927 CST and taken to NAS Pensacola for treatment. The pilot of T-28 Side No. 254 reported seeing a second parachute about two miles north east of the student pilot. A combined search by personnel in T-28's and rescue helicopters located the parachute hung up in a tree in a gully where it had been reported to be. The helicopters were unable to hover over the chute and could not land near it. A ground party arrived (NAS Whiting crash crew) and a concerted effort made to reach the parachute. It was later determined to be a parachute flare and not a personnel chute.

The search effort was re-diverted to the crash site in an attempt to find the instructor pilot. The crash crew arrived at the site and discovered the pilot's body in the aforementioned position.

The weather at the time of the accident was 10,000 feet broken, high overcast, and 7 miles visibility. (b) (5)

(b) (5)

PAGE 7 of 17 PAGES

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6 SERIES

PART VI - DAMAGE TO THE AIRCRAFT.

The aircraft received alfa damage as a result of collision with the ground and fire after impact as indicated by enclosure (5). Angle of impact is estimated to be 70°. The upper and lower right engine cowlings separated from the aircraft prior to impact and were located 748 yards from the crash site. Both sections of the cowling evidenced areas of intense heat. (See enclosure 6, 7 and 8)

PART VII - THE INVESTIGATION AND ANALYSIS

(b) (5)



(b) (5)



PAGE 9 of 17 PAGES

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPM/VINST 3750.6 SERIES

(b) (5)

A solid black rectangular redaction box covering the top portion of the page content.

(a) PERSONNEL FACTORS

(b) (5)

A large solid black rectangular redaction box covering the majority of the page content, starting below the section header and ending above the footer.

(b) (5)



PAGE 11 of 17 PAGES
SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPM. VINST 3750.6 SERIES

(b) (5)



(2) Maintenance Factors - (b) (5)

(b) (5)



SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OFM/VINST 3750.6 SERIES

(b) (5)



PAGE 13 OF 17 PAGES

SPECIAL HANDLING REQUIRED IN ACCORDANCE WITH OPNAVINST 3750.6 SERIES

(b) (5)



(b) (5)



PART VIII - CONCLUSIONS

(b) (5)



(b) (5)



(b) (5)

